

United States Of America  
Department of Transportation - Federal Aviation Administration

# Supplemental Type Certificate

*Number* SA09030SC

ST3813SC-A (KAW)

*This Certificate issued to* Texas Skyways, Inc.  
308 Boerne Stage Airfield  
Boerne, TX 78006

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Air Regulations.*

*Original Product - Type Certificate Number:* 5A6

*Make:* Cessna

*Model:* 180

*Description of Type Design Change:* Installation of Hartzell Propeller Model PHC-G3YF-1RF/F7691 and Spinner Assembly D5732 or C4582 in accordance with Texas Skyways, Inc. Installation Procedures 94H2, dated 08/31/94, or later FAA approved revision.

*Limitations and Conditions:* Approval of this change in type design applies to the following:

Cessna Model 180, S/N 31260 through 18052770, equipped with Continental O-470-K, -L, -R, or -S engine. Airplane Flight Manual Supplement 94H9-1, dated 12/20/94, or later FAA approved revision is required.

(See continuation sheet)

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* August 22, 1994

*Date of issuance:* December 20, 1994

*Date reissued:*

*Date amended:*



*By direction of the Administrator*

*Gary Bloach*  
(Signature)

for J. J. Merrill  
Manager, Special Certification Office  
Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of the Supplemental Type Certificate.

The FAA will reissue the certificate in the name of the transferee and forward it to him.

---

### TRANSFER ENDORSEMENT

Transfer the ownership of Supplemental Type Certificate Number \_\_\_\_\_

to (Name of transferee) \_\_\_\_\_

(Address of transferee) \_\_\_\_\_

(Number and street)

(City, State, and ZIP code)

from (Name of grantor) (Print or type) \_\_\_\_\_

(Address of grantor) \_\_\_\_\_

(Number & street)

(City, State, and ZIP code)

Extent of Authority (if licensing agreement): \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Date of Transfer: \_\_\_\_\_

Signature of grantor (In ink): \_\_\_\_\_

United States Of America  
Department of Transportation - Federal Aviation Administration

**Supplemental Type Certificate**  
(Continuation Sheet)

*Number* SA09030SC

Date of Issuance: December 20, 1994

*Limitations and Conditions* (Continued):

Cessna Model 180, S/N 18052771 and subsequent, equipped with Continental O-470-U engine. Airplane Flight Manual Supplement 94H9-4, dated 12/20/94, or later FAA approved revision is required.

Cessna Model 180, S/N 31260 through 18052770, modified in accordance with STC SA8842SW. Airplane Flight Manual Supplement 94H9-5a, dated 12/20/94, or later FAA approved revision is required.

Cessna Model 180, S/N 31260 and subsequent, modified in accordance with STC SA8950SW. Airplane Flight Manual Supplement 94H9-6a, dated 12/20/94, or later FAA approved revision is required.

Compatibility of this design change with previously approved modifications must be determined by the installer. A copy of this Certificate, Continuation Sheet and appropriate Airplane Flight Manual Supplement(s) must be maintained as part of the permanent records for the modified aircraft.

-End-

---

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.